



ITEM	DESCRIPTION	COMPLETE REPAIR PLUS 10-86574	COMPLETE REPAIR KIT 10-86046	REPAIR PARCIAL 10-80003	SPRING KIT 10-80010	CONJUNTO TRANSMISSION KIT 10-80020
1	BUSHING VOLVO	1	1	-	-	-
2	BUSHING SCANIA	1	1	-	-	-
3	BUSHING MERCEDES	1	1	-	-	-
4	WORM Gear	1	1	1	-	1
5	FRONT Cover	1	1	-	-	-
6	BEARING	1	1	-	-	-
7	EXPANSIVE COVER	1	1	1	1	-
8	GEAR	1	1	1	-	1
9	COUPLING	1	1	1	-	1
10	REAR COVER	1	1	-	-	-
11	LINING	1	1	1	-	-
12	RACK	1	-	-	-	-
13	SCREW	6	6	6	-	-
14	RIVET	5	5	5	5	-
15	THUST WASHER	1	1	1	-	-
16	O'RING WORM GEAR	1	1	1	1	-
17	O'RING OF RACK	2	2	2	2	-
18	JUNCTION	1	1	1	1	-
19	AXIAL BEARING	1	1	1	-	-
20	COUPLING SPRING	1	1	1	1	1
21	IINTERNAL SPRING	1	1	1	-	-
22	EXTERNAL SPRING	1	1	1	-	-
23	COMPRESSION SPRING	1	1	1	-	-
24	ASSEMBLY INSTRUCTION	1	1	-	-	-